UK CA 0086

BS EN149:2001+A1:2009
Single-Use Particle Filtering Half Mask
User Instruction

FFP3 NR



CDN-P3 (Standard)



CDN-P3C (Carbon Layer)



CDW-P3 (Standard)



CDW-P3C (Carbon Layer)

Manufacturing date: see minimum packing

Check before use

Approved Body: No. 0086
BSI Assurance UK Ltd
Address: Davy Ave, Knowlhill, Milton Keynes, MK5 8PP, United Kingdom

Manufacturer
Jiangyin Chang-hung Industrial Manufacturing Factory LLC
Address: Industrial Park, NO.16, Huan Nan Road, Huang Tang, XiaKe Town, Jiangyin City, JiangSu, China.

UK declaration of conformity
https://pse.is/C8WLM

Revision: 210301

BS EN149: 2001+A1:2009 standard:

Complies with the requirements of the PPE Regulation (EU)2016/425.Three protection classification – Filter efficiency against particulate aerosols is greater than 80%(FFP1), 94%(FFP2), 99% (FFP3). Classification is showed on the mask.Regulation 2016/425 on personal protective equipment as brought into UK law and amended.

Product Marking explanation

Example: GRANDE UK CA CDN-P3C 0086 BS EN149:2001+A1:2009 FFP3 NR	GRANDE →Identification of manufacturer CDN-P3C → Product model name BS EN149:2001+A1:2009 → Standard	FFP3 → Protection classification NR → Single shift use only UK CA → UKCA mark 0086 → Approved Body

Check prior to use:

Careful observance of these instructions is an important step in safe use.

1. Check the face seal is welded well.
2. Check the nosepiece is glued closely on the mask.
3. Check the valve is set up well.
4. Check the valid date which is showed on the box.

Fitting instructions:

1. Cup the mask in your hand with the nosepiece at your fingertips allowing the headbands to hang freely below your hand.
2. Cup the mask firmly against your face with the nosepiece on the bridge of your nose.
3. Pull the bottom strap over your head and position it around the neck below the ears. Pull the top strap over your head resting it high at the top back of your head.
4. CDW-P3 and CDW-P3C have adjustable strap buckle. Adjust tension by pulling head-straps with both hands. Decrease it by pushing out on the back of the buckle.
5. Check the face seal is fully fitted your face. Press soft nosepiece to conform snugly around the nose.
6. (a) To test fit for mask without exhalation valve: Cup both hands over the mask. Then inhale and exhale vigorously. (b) To test fit for mask with exhalation valve: Cup both hands over the mask and inhale sharply.
7. When inhale, a negative pressure should be felt inside mask. If any leakage is detected, adjust position of mask and/ or tension of strap. Retest the seal, and repeat the procedure until the mask is sealed properly.

Warnings:

1. Failure to follow all instructions and limitations on the use of this product could reduce the effectiveness of the mask and result in sickness or death.
2. A properly selected mask is essential to protect your health. Before using this mask, consult an industrial hygienist or Occupational Safety Professional to determine the suitability for your intended use.
3. This mask does not supply oxygen and must not be used in atmospheres containing less than 19.5% oxygen.
4. Do not use when concentrations of contaminants are immediately dangerous to health or life.
5. Do not use the mask in an explosive environment.
6. Natural rubber strap may cause allergic to certain people, advise the user to stop using the mask if this happen
7. Leave work area immediately and return to fresh air if breathing becomes difficult, or other distress occurs.
8. Do not use with beards or other facial hair that may inhibit contact between the face and the edge of the mask.
9. Never alter, modify or abuse this mask.
10. Do not use for more than one shift (8hours). No maintenance necessary. Discard the used mask after use.
11. Change this mask immediately if breathing becomes difficult or the mask becomes damaged or distorted, or a proper face fit can't be maintained.
12. Store unused masks in box in a clean, dry, non-contaminated area.
13. Masks need to be transported in a carton.





Figure 12c-Temperature range of storage conditions



Figure 12d-Maximum relative humidity of storage conditions


Figure 12b-See information supplied by the manufacturer

Dat e of expiry： 3 years